




Control - Nyquist Design Method Gain / Phase Margins



Close Loop / Feedback Control



The Design Process of a Control System

- **Step 1: Goal, variables and, specifications**
 - Establish the control goals or requirements
 - Identify the variables to be controlled
 - Write the specifications based on the requirements
- **Step 2: System definition and modeling**
 - Establish the system configuration (select sensors & actuators)
 - functional block diagram
 - Signal flow diagram
 - State space presentation
 - In case of multiple blocks, simplify the block diagram to a standard close loop system diagram
 - Obtain a model of the process, the actuator and the sensor
- **Step 3: Control system design simulation and analysis**
 - Describe the controller and select key parameters to be adjusted
 - Optimize the parameters and **analysis / simulate** the performance
- If the performance meets the specifications or the relaxed specifications – Finalize the design (End)
- Else iterate the configuration (go to step 2)


NEUTRAL STABILITY



$$|KG(s)| = 1$$


$$\angle B(s) = -180$$

stability
criteria



Gain & Phase Margin – Introduction


Gain Margin – Concept



- **Gain Margin (GM)** – The factor by which the gain can be raised before instability results.
- Measure The vertical distance between curve and the $|KG(j\omega)|$ line at a frequency where $\angle KG(j\omega) = 180$


Notes

- GM is a factor by which the gain K can be raised before the instability results
- The system is unstable when $|KG(j\omega)| < 1$ $GM < 0dB$
- The GM can also be determined from the root locus with respect to K by noting two values of K : (1) at the point where the locus crosses the $j\omega$ -axis and (2) at the nominal close loop poles. The GM is the ratio between these two values.



$$GM = \frac{k_{jw}}{k_{cl}}$$

Phase Margin – Concept



- **Phase Margin (PM)** – The amount by which the phase of $\angle KG(j\omega)$ exceeds -180° when $|KG(j\omega)|=1$
- How much phase lag the system can tolerate before it goes unstable.


$$PM \approx \frac{\xi}{100}$$

- **Crossover Frequency (ω_c)** – The frequency at which the gain is unity or 0 db

BODE THEOREM

$$\begin{aligned} \text{SLOPE OF } |KG| &\triangleq \text{PHASE } \angle GH \\ -1 &\Rightarrow -90^\circ \\ -\frac{2}{3} &\Rightarrow -180^\circ \end{aligned}$$

* FOR A GOOD STABILITY




\rightarrow CROSS $|KG| = 1$ WITH
A SLOPE OF -1

$$\Rightarrow \angle KG = 90^\circ \left[\gamma = \frac{90}{180} = 0.9 \right]$$

* THE LEAD/LAG COMPENSATOR CAN HELP TO FIX THE SLOPE TO BE CLOSE TO -1

Bode Design




Requirement for KG

	KG	WHY	FREQ.
$\frac{Y}{V} = \frac{KG}{1+KG} ; \frac{Y}{V} \rightarrow 0$	SMALL KG	• Reject noise from the sensor	HIGH
$\frac{Y}{D} = \frac{G}{1+KG} ; \frac{Y}{D} \rightarrow 0$	LARGE KG	• Reject disturbance	LOW
$\frac{Y}{R} = \frac{KG}{1+KG} ; \frac{Y}{R} \rightarrow 1$	LARGE KG	• Good Tracking	LOW

Bode Design - GENERAL APPROACH

THE COOKBOOK



- I Increase gain k
 - Meet steady state error req.
 - Meet bandwidth req.

- II Use a Lead comp.
 - Increase the PM
 - Problem
 - Atten - low freq
 - Ampl - High Freq

- III Use a Lag comp. (or LP)
 - Fix the gain at low freq.

Bode Design – Guidelines

- **Step 1 – Gain K** – Determine open loop gain K to satisfy (1) **steady state error** or (2) **frequency bandwidth** requirements
 - **1.1 Steady State Error** - To meet the steady state error requirements pick K to satisfy steady error e_{ss}

$$\frac{E(s)}{R(s)} = \frac{1}{1 + KG(s)} \Rightarrow E(s) = \left[\frac{1}{1 + KG(s)} \right] \cdot R(s)$$


$$e_{ss} = e(t \rightarrow \infty) = \lim_{s \rightarrow 0} s \left[\frac{1}{1 + KG(s)} \right] R(s)$$

\uparrow FVT \uparrow




Bode Design – Guidelines

- **1.2 Frequency Bandwidth** - Pick K such that the open loop cross over frequency (ω_{co}) is below the desired close loop frequency bandwidth by a factor of 2



Bode Design – Guidelines

- **Step 2 – Lead Compensator –**
 - 2.1 - Evaluate the PM of the uncompensated system using the value of K obtained from Step 1.2




Bode Design – Guidelines


- **Step 2 – Lead Compensator –**

- 2.2 - Allow for extra margin (~ 10 deg) and determine the needed phase lead ϕ_{\max} (added by the lead compensator)

OPTION 1




OPTION 2



Bode Design – Guidelines


- Step 2 – Lead Compensator –

- 2.3 – Adjusting the parameters of the Lead - Determine the α of the lead compensator.



$$K(s) = \sqrt{\alpha} \frac{s + \frac{\omega_o}{\sqrt{\alpha}}}{s + \omega_o \sqrt{\alpha}}$$

$$K(s) \Big|_{s \rightarrow 0} = \sqrt{\alpha} \cdot \frac{\frac{\omega_o}{\sqrt{\alpha}}}{\omega \sqrt{\alpha}} = \frac{1}{\sqrt{\alpha}}$$




$$\rightarrow \phi_{max} = \tan^{-1} \sqrt{\alpha} - \tan^{-1} \frac{1}{\sqrt{\alpha}}$$

Bode Design – Guidelines

- **Step 2 – Lead Compensator –**

- **2.4 – Adjusting the parameters of the Lead** - Pick ω_0 to be the cross over frequency

$$K(s) = \sqrt{\alpha} \frac{s + \frac{\omega_{co}}{\sqrt{\alpha}}}{s + \omega_{co} \sqrt{\alpha}}$$



- **2.5 – Bode Plot** - Draw the compensator frequency response and check the PM
- **2.6 – Design Iteration** - Iterate on the design and adjust the poles , zeros and gain
- **2.7 – Additional Leads** - Add an additional lead compensator (i.e. a double lead compensator)

- **Note – Max PM per lead compensator is 70 Deg**

Bode Design – Guidelines

- **Step 3 – Lag Compensator –**

- **3.1 – Gain K Adjustment**

- Determine the open loop gain K that will meet the PM requirements without compensation.


OR

- Determine the open loop gain K that is still needed to meet the Steady State error – e_{ss}

- **3.2 - Bode Plot** - Draw the bode plot of the open loop system with the cross over frequency and evaluate the low frequency gain.

Bode Design – Guidelines

- Step 3 – Lag Compensator –
 - 3.3 – Adjusting the parameters of the lead compensator
 - Determine the α of the lead compensator




$$K(s) = \frac{s + \omega_0 \sqrt{\alpha}}{s + \frac{\omega_0}{\sqrt{\alpha}}}$$

$$K(s) \Big|_{s \rightarrow 0} = \frac{\omega_0 \sqrt{\alpha}}{\frac{\omega_0}{\sqrt{\alpha}}} = \alpha$$

Bode Design – Guidelines

- Step 3 – Lag Compensator –
 - 3.4 – Adjusting the parameters of the lead compensator
 - Choose the cross over frequency ω_o of the lag (zero of the lag compensator) to be 1 octave to 1 decade below the new cross over frequency



MOST CRITICAL DESIGN
 SET W_o OF THE LAG
 ALL THE WAY TO THE LEFT
 FROM THE W_{co}

$$5W_o = \frac{W_{co}}{10}$$

$$W_o = \frac{W_{co}}{50}$$

- Design Iteration – Iterate on the design and adjust the compensator parameters (pole , zero gain) in order to meet all the specs.

BODE DESIGN


(1) STEP 1- GAIN K - Determine open loop gain K to satisfy error bandwidth requirements

1.1 ERROR - To meet error requirement pick K to satisfy steady state error e_{ss}


$$\frac{E(s)}{R(s)} = \frac{1}{1+KG(s)} \Rightarrow E(s) = \frac{1}{1+KG(s)} R(s)$$

$$e_{ss} = e(t \rightarrow \infty) = \lim_{s \rightarrow 0} s \left[\frac{1}{1+KG} \right] R(s)$$

NOTE




1.2 BANDWIDTH - Pick K so that the open loop crossover (ω_{co}) frequency is a factor of 2 below the desired close-loop bandwidth



(2) STEP 2 - LEAD


2.1 Evaluate the PM of the uncompensated system using the value of K obtained from step 1.2



2.2 Allow for extra margin ($\sim 10^\circ$) and determine the needed phase lead ϕ_{max} (added by the lead comp.)


OPTION 1

OPTION 2




2.3 Determine α

$$K|_{s \rightarrow 0} = \sqrt{\alpha} \frac{\omega_0}{\omega_0 \sqrt{\alpha}} = \sqrt{\alpha} \frac{\omega_0}{\omega_0 \sqrt{\alpha}} = \frac{1}{\sqrt{\alpha}}$$



$$K(s) = \sqrt{\alpha} \frac{s + \frac{\omega_0}{\sqrt{\alpha}}}{s + \omega_0 \sqrt{\alpha}}$$




$$\phi = \tan^{-1} \sqrt{\alpha} - \tan^{-1} \frac{1}{\sqrt{\alpha}}$$

2.4 Pick ω_0 to be the crossover frequency

$$\omega_0 = \omega_{c0}$$

$$K(s) = \sqrt{\alpha} \frac{s + \frac{\omega_0}{\sqrt{\alpha}}}{s + \omega_0 \sqrt{\alpha}}$$



2.5 Draw the compensated frequency response and check the PM

2.6 Iterate on the design
Adjust poles, zeros and Gain

2.7 Add an additional lead compensator (i.e. a double-lead compensator)

MAX PM PER LEAD COM. IS 70°

③ STEP 3 - LAG


3.1 Determine the open loop gain K that will meet the PM requirement with out compensation

OR

[Determine the open loop gain K that is still needed to meet the e_{ss}


3.2 Draw the Bode plot of the open loop system with the cross over freq. and evaluate the low frequency gain

3.3 Determine α to meet the low frequency gain based on the steady state req.



$$K(s) = \frac{s + \omega_0 \sqrt{\alpha}}{s + \frac{\omega_0}{\sqrt{\alpha}}} \rightarrow_{s \rightarrow 0} K(0) = \alpha$$

3.4 Choose the corner frequency (ZERO of the lag compensator to be 1 octave to ~~a~~ decade below the new cross over frequency




3.5 Iterate on the design. Adjust compensator parameters (poles, zeros, gain) to meet all specs.

P 356 K, LEAD ? BLUE
P 361-362 LAG BOX

BODE DESIGN - EXAMPLE

$$G(s) = \frac{1152}{(s+9)(s^2 + 16s + 128)}$$



$$\zeta = 0.65$$

$$\zeta = \frac{PM}{100}$$

$$\omega_{co} = 4.75 \text{ Hz}$$


$$\phi M = 65 \Rightarrow 180 - 65 = 115$$

$$E_{ss} < 1\%$$

T 6210 Lead 5

Bode Design – Example

$$G(s) = \frac{1152}{(s+9)(s^2+16s+128)}$$



STEP 1 (K)

$$W_{co} = 4.75 \text{ Hz} = 4.75 \frac{\text{cycle}}{\text{sec}} \frac{2\pi \text{ RAD}}{1 \text{ cycle}} = 29.84 \frac{\text{RAD}}{\text{sec}}$$

• FROM THE BODE GRAPH

• FOR $W_{co} \approx 30 \text{ RAD/sec} \rightarrow |G(s)| = 0.04$

• CHOOSE K_o TO GET $W_{co} \approx 30 \text{ RAD}$

$$|K_o G|_{W_{co}} = 1$$


$$K_o = \frac{1}{|G|_{W_{co}}} = \frac{1}{0.04} = 25$$

STEP 2 (LEAD)

• ADD PM WITH A LEAD

AT $W_{co} \quad \angle G|_{W_{co}} \approx -225$

• FOR $PM \approx 65 \quad \angle G|_{W_{co}} \geq -115$




• NEED TO ADD 110°

$\angle G|_{W_{co}} = -225 \xrightarrow{\text{Add } 110^\circ} -115$

-3-

- TO ADD 140° (TOO MUCH FOR A SINGLE LEAD - TYPICALLY ADD UP TO 70° PM)

\Rightarrow ADD TWO LEADS @ 55°




$$K(s) = \sqrt{\alpha} \frac{s + \frac{W_0}{\sqrt{\alpha}}}{s + W_0 \sqrt{\alpha}}$$

\rightarrow SEE GRAPH (FIG 6.54)


FOR PM $\approx 55^\circ$

$$\alpha = 10$$

$$W_0 = 30$$



$$\text{phase } \phi = \tan^{-1} \sqrt{10} - \tan^{-1} \frac{1}{\sqrt{10}} = 72.45^\circ - 17.38^\circ = 55^\circ$$




FOR ONE LEAD

$$K(s) = \sqrt{10} \frac{s + \frac{30}{\sqrt{10}}}{s + 30\sqrt{10}}$$

FOR TWO LEADS

$$K(s) = 10 \left(\frac{s + 9.48}{s + 94.86} \right)^2$$

FOR $s \rightarrow 0$ $|K| = 10 \cdot (0.1)^2 = 0.1$



COMBINED CONTROLLER

$$K(s) = K + K(\text{LEAD})$$

$$= 25 \cdot 10 \left(\frac{s + 9.48}{s + 94.86} \right)^2$$

$$= 250 \left(\frac{s + 9.48}{s + 94.86} \right)^2$$

$$e_{ss} = \lim_{s \rightarrow 0} s \left[\frac{1}{1 + K(s)G(s)} \right] R(s)$$

$$e_{ss} = \lim_{s \rightarrow 0} s \left[\frac{1}{1 + K(s)G(s)} \right] \frac{1}{s}$$

$$= \frac{1}{1 + K(0)G(0)}$$

$$G(s) \Big|_{s=0} = \frac{1152}{(s+4)(s^2+16s+128)} \Big|_{s=0} = \frac{1152}{4 \cdot 128} = 1$$

$$K(s) \Big|_{s=0} = 250 \left(\frac{s+9.48}{s+94.96} \right)^2 \Big|_{s=0} = 250 \cdot \left(\frac{1}{10} \right)^2 = 2.5$$

$$e_{ss} = \frac{1}{1 + 2.5} = 0.285$$

$$e_{ss} < 0.01$$

$$\frac{1}{1+K} = 0.01$$


$$1 = 0.01 + 0.01K$$

$$0.99 = 0.01K$$

$$K = 99 \approx 100$$

$$\text{NEW } K = \frac{100}{2.5} = 40$$

LAG



$$K(s) = \frac{s + W_0 \sqrt{X}}{s + \frac{W_0}{\sqrt{X}}}$$


1 decade below the W_{CO}


$$s \rightarrow 0 \quad \frac{W \sqrt{X}}{\frac{W_0}{\sqrt{X}}} = W \sqrt{X} \frac{\sqrt{X}}{W} = X$$

$$W_0 = 0.6 \frac{\text{RAD}}{\text{SEC}}$$

$$X = 40$$

$$K(s) = \frac{s + 0.6 \sqrt{40}}{s + 0.6/\sqrt{40}} = \frac{s + 3.79}{s + 0.09}$$






$$\begin{aligned} \Delta &= \tan^{-1} \frac{1}{\sqrt{x}} - \tan^{-1} \sqrt{x} = \tan^{-1} \frac{1}{\sqrt{40}} - \tan^{-1} \sqrt{40} \\ &= 8.98 - 81.00 \approx 71^\circ \end{aligned}$$

6.32 6.32


Bode Design – Example

$$G(s) = \frac{1152}{(s+9)(s^2+16s+128)}$$




Bode Design – Example

$$G(s) = \frac{25 \cdot 1152}{(s + 9)(s^2 + 16s + 128)}$$




Bode Design – Example


$$G(s) = \frac{25 \cdot 1152}{(s+9)(s^2+16s+128)} \cdot 10 \left(\frac{s+9.48}{s+94.86} \right)^2$$



Bode Design – Example

$$G(s) = \frac{25 \cdot 1152}{(s+9)(s^2+16s+128)} \cdot 10 \left(\frac{s+9.48}{s+94.86} \right)^2 \cdot \left(\frac{s+3.79}{s+0.09} \right)$$





Bode Design – Example (Matlab)

- `s = tf('s');`
 - `sys = 1152/((s+9)*(s^2 + 16*s + 128));`
 - `bode(sys)`
 - `grid on`
 - `sys1 = 25*1152/((s+9)*(s^2 + 16*s + 128));`
 - `hold on`
 - `bode(sys1)`
 - `sys2=sys1* 10*((s+9.48)/(s+94.86))^2`
 - `hold on`
 - `bode(sys2)`
 - `sys3=sys2*((s+3.79)/(s+0.09))`
 - `hold on`
 - `bode(sys3)`
-